

FIG. 1
PRIOR ART




FIG. 2




FIG. 3




FIG.4




FIG. 6

—
CHECKLIST
▽
△

- SR SERVICE
- GUI SERVICE
- MI SERVICE
- LR SERVICE
- SR SERVICE

↶

↷

701

FIG. 7

☐ Checklist Quarterly PM

Task Description	Value	Optional	Floating	Status	Last Update
<input checked="" type="checkbox"/> Started PM		No	No	Completed	01 June-2000 10:15 AM
<input checked="" type="checkbox"/> Base pressure reading		Yes	Yes	Redone	01 June-2000 10:20 AM
<input checked="" type="checkbox"/> CH-18 Pressure (INIT)	23.75	Yes	Yes	Completed	02 June-2000 08:00 AM
<input checked="" type="checkbox"/> CH-18 Pressure (FINAL)	23.50	Yes	Yes	Completed	02 June-2000 08:10 AM
<input checked="" type="checkbox"/> Standard Pressure (INIT)	25.00	Yes	Yes	Completed	02 June-2000 08:20 AM
<input checked="" type="checkbox"/> Standard Pressure (FINAL)	25.00	Yes	Yes	Completed	02 June-2000 08:25 AM
<input checked="" type="checkbox"/> Collect Base Pressure readings		Yes	No	Completed	02 June-2000 08:30 AM
<input checked="" type="checkbox"/> Process Monthly PM checklist		No	No	Started	02 June-2000 10:30 AM
<input checked="" type="checkbox"/> Track assembly-17 data		No	No		
<input checked="" type="checkbox"/> Assembly-17 repair data		Yes	No		
<input checked="" type="checkbox"/> Start Workflow (ABC)		No	No		
<input checked="" type="checkbox"/> Read WorkInstruction (ABC)		Yes	Yes	Completed	01 June-2000 10:30 AM

Comments for the selected step

Started Monthly checklist

OK Close Close All Help

FIG. 8




FIG. 9

10/10




FIG. 10